

VT6120/VT6122/VT6130/VT6132
Utility Package (VIA version)
Version: 3.1

1. Major changes in this software packages

GigaCheck can support Windows Vista X86 since this version.

2. Detailed change note list

2.1. Application utilities

Name	Ver.	Support OS	Location	Note
GigaCheck	2.35	Windows 98, Windows 98SE, Windows ME, Windows 2000, Windows XP X86, Windows Server 2003 X86, Windows Vista X86	\GigaCheck\	From 2.21 to 2.35: 1. NDIS5 Miniport driver (1.59). 2. NDIS6 Miniport driver (1.28). 3. Winsetup (3.31).
DMI-GE	1.24	Windows 98SE, Windows ME, Windows 2000, Windows XP X86, Windows Server 2003 X86	\DMI-GE\	From 1.22 to 1.24: 1. NDIS5 Miniport driver (1.59). 2. Winsetup (3.31).
VSNMP-GE	1.25	Windows 98, Windows 98SE, Windows NT4.0, Windows ME, Windows 2000, Windows XP X86, Windows Server 2003 X86	\VSNMP-GE\	From 1.23 to 1.25: 1. NDIS5 Miniport driver (1.59). 2. Winsetup (3.31).

2.2. Application documents

Document	Ver.	Location	Note
GigaCheck User Guide	1.60	\GigaCheck\	1. No version change in this software package.
DMI-GE User Guide	1.40	\DMI-GE\	1. No version change in this software package.
VSNMP-GE User Guide	1.50	\VSNMP-GE\	1. No version change in this software package